



TIIGER POLE PULLERS

THE CHALLENGE

A Virginia utility company had several instances in which line truck booms were damaged by pulling old poles out of the ground using the winch line on the line truck. This is a practice that is strictly forbidden by truck manufacturers, to the point that if a boom is damaged and there is no pole puller on the truck, the warranty is voided.

THE SOLUTION

The utility company now carries pole pullers on each line truck and requires any contractors working on their system to do the same.

One of their contractors purchased 120 Pole Pullers and Tiiger shipped them to 3 different states in less than 3 weeks.



THE CHALLENGE

Damaged Line Truck Booms

THE SOLUTION

Tiiger Pole Pullers on every line truck

THE RESULT

No more line truck damage as the result of pole pulling

